

Structural problems

A1 Area with problems of substratum differential settlement (see structural study) A2 Differential settlement of foundation (see structural study) A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification A5 Area of the masonry which needs conservation A6 Area of the extrados of the domes which needs consolidation A7 Unknown preservation state of the extrados of the arcade dome A8 Areas of the masonry which need additions Construction works **B1** Poorly constructed cornice of cement mortar **B2** Area with problems in draining rainwater

B3 Absence of Altar **B4** Poorly constructed cover plate of the well which leads to the underground galleries of the Agiasma B5 Spring of the Agiasma showing traces of form alterations B6 Blocked window **B7** Surface of the masonry which needs conservation **B8** Area where steps need to be constructed in order to improve the transition from one level to the other **B9** Stone steps showing local problems of detachments and fragmentation of their compartments B10 Absence of access to the sea B11 Areas of render showing decay

Floors

C1 Area below the recent floor which needs excavational research

C2 Recent floor of cement tiles which was laid 10-15cm higher than the original one C3 Problems of rising dampness C4 Recent floor of cement tiles which needs replacement C5 Poorly constructed floor of cement mortar

C6 Stone floor in a bad preservation state and with poor concrete repairs C7 Poor repair of the steps with cement mortar

Joinery - doors & windows

D1 Absence of icon screen **D2** Absence of furniture of the Prothesis D3 Existing masonry recess D4 Timber 19th C doorway D5 Absence of door D6, D7, D8 Absence of window

Installations

E1 Unknown preservation state of the Agiasma supply E2 Water overflow in high locations of the arcades of the Agiasma

E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved **F2** Position of the cover plate of the well which needs excavational research

F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater

F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the

descending staircase F6 Absence of handrail

F7 Absence of railings



In collaboration with the Technical Committee on Cultural Heritage


ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS


RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: PLAN OF LEVEL A' 1:50 Scale:







Structural problems A1 Area with problems of substratum differential

settlement (see structural study) A2 Differential settlement of foundation (see structural study) A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification A5 Area of the masonry which needs conservation A6 Area of the extrados of the domes which needs consolidation A7 Unknown preservation state of the extrados of the arcade dome A8 Areas of the masonry which need additions Construction works

B1 Poorly constructed cornice of cement mortar B2 Area with problems in draining rainwater B3 Absence of Altar B4 Poorly constructed cover plate of the well which leads to the underground galleries of the Agiasma B5 Spring of the Agiasma showing traces of form alterations B6 Blocked window **B7** Surface of the masonry which needs conservation

B8 Area where steps need to be constructed in order to improve the transition from one level to the other **B9** Stone steps showing local problems of detachments and fragmentation of their compartments B10 Absence of access to the sea B11 Areas of render showing decay

Floors

C1 Area below the recent floor which needs excavational research

C2 Recent floor of cement tiles which was laid 10-15cm higher than the original one

C3 Problems of rising dampness C4 Recent floor of cement tiles which needs replacement

C5 Poorly constructed floor of cement mortar

C6 Stone floor in a bad preservation state and with poor

concrete repairs

C7 Poor repair of the steps with cement mortar

Joinery - doors & windows

D1 Absence of icon screen D2 Absence of furniture of the Prothesis D3 Existing masonry recess D4 Timber 19th C doorway

D5 Absence of door D6, D7, D8 Absence of window

Installations

E1 Unknown preservation state of the Agiasma supply

piping **E2** Water overflow in high locations of the arcades of the

Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved

F2 Position of the cover plate of the well which needs excavational research

- F3 osition of the old wall of the dock which has been
- covered by the rocks of the breakwater
- F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the
- descending staircase
- F6 Absence of handrail
- F7 Absence of railings



in collaboration with the Technical Committee on Cultural Heritage

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: PLAN OF LEVEL B' 1:50 Scale:

May 2007 Rev. February 2016 Date: Plate number: MCE02





B6 Blocked window
B7 Surface of the masonry which needs conservation
B8 Area where steps need to be constructed in order to improve the transition from one level to the other
B9 Stone steps showing local problems of detachments and fragmentation of their compartments
B10 Absence of access to the sea
B11 Areas of render showing decay

Floors

C1 Area below the recent floor which needs excavational research

C2 Recent floor of cement tiles which was laid 10-15cm higher than the original one

higher than the original one C3 Problems of rising dampness

C4 Recent floor of cement tiles which needs replacement

C5 Poorly constructed floor of cement mortar

C6 Stone floor in a bad preservation state and with poor

concrete repairs C7 Poor repair of the steps with cement mortar

Joinery - doors & windows

D1 Absence of icon screen D2 Absence of furniture of the Prothesis

D3 Existing masonry recess D4 Timber 19th C doorway D5 Absence of door

D6, D7, D8 Absence of window

Installations

E1 Unknown preservation state of the Agiasma supply piping

piping E2 Water overflow in high locations of the arcades of the Agiasma

E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preservedF2 Position of the cover plate of the well which needs excavational research

F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater

- **F4** Potential area for creating a new courtyard
- **F5** Recent parapet which has blocked the use of the descending staircase
- F6 Absence of handrail
- F7 Absence of railings



ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)




UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: PLAN OF LEVEL C' 1:50 Scale:

> May 2007 Rev. February 2016

Date:

Plate number: MCE03

Whitish plaster Render of cement mortar Partial sealing with cement mortar Floors Paint C1 Area below the recent floor which needs excavational research Loss-erosion C2 Recent floor of cement tiles which was laid 10-15cm Construction works of render higher than the original one **C3** Problems of rising dampness B1 Poorly constructed cornice of cement mortar Loss of pointing Structural problems B2 Area with problems in draining rainwater A1 Area with problems of substratum differential B3 Absence of Altar C4 Recent floor of cement tiles which needs replacement settlement B4 Poorly constructed cover plate of the well which leads C5 Poorly constructed floor of cement mortar Erosion of stone to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form C6 Stone floor in a bad preservation state and with poor (see structural study) A2 Differential settlement of foundation concrete repairs Extensive erosion of stone (see structural study) alterations B6 Blocked window A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification B7 Surface of the masonry which needs conservation Joinery - doors & windows Loss of stone A5 Area of the masonry which needs conservation **B8** Area where steps need to be constructed in order to D1 Absence of icon screen A6 Area of the extrados of the domes which needs improve the transition from one level to the other Crack consolidation D3 Existing masonry recess B9 Stone steps showing local problems of detachments D4 Timber 19th C doorway A7 Unknown preservation state of the extrados of the and fragmentation of their compartments ААПЗ Test sample D5 Absence of door arcade dome B10 Absence of access to the sea D6, D7, D8 Absence of window A8 Areas of the masonry which need additions B11 Areas of render showing decay



D2 Absence of furniture of the Prothesis


C7 Poor repair of the steps with cement mortar

Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings



RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE

RIZOKARPASSO, CYPRUS

Implemented by the:

n collaboration with the

Technical Committee on Cultural Heritage

UNDP

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)


ENVIRONMENT OF THE MONASTERY



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: **SECTION 1-1** 1:50 Scale: May 2007 Rev. February 2016 Date:

Plate number: MCE04

Whitish plaster Render of cement mortar Partial sealing with cement mortar Floors Paint C1 Area below the recent floor which needs excavational research Loss-erosion C2 Recent floor of cement tiles which was laid 10-15cm Construction works of render higher than the original one **C3** Problems of rising dampness B1 Poorly constructed cornice of cement mortar Loss of pointing Structural problems B2 Area with problems in draining rainwater A1 Area with problems of substratum differential B3 Absence of Altar C4 Recent floor of cement tiles which needs replacement C5 Poorly constructed floor of cement mortar settlement B4 Poorly constructed cover plate of the well which leads Erosion of stone (see structural study) to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form C6 Stone floor in a bad preservation state and with poor A2 Differential settlement of foundation concrete repairs C7 Poor repair of the steps with cement mortar Extensive erosion of stone (see structural study) alterations B6 Blocked window A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification B7 Surface of the masonry which needs conservation Joinery - doors & windows Loss of stone A5 Area of the masonry which needs conservation **B8** Area where steps need to be constructed in order to D1 Absence of icon screen A6 Area of the extrados of the domes which needs **D2** Absence of furniture of the Prothesis improve the transition from one level to the other Crack consolidation D3 Existing masonry recess B9 Stone steps showing local problems of detachments D4 Timber 19th C doorway A7 Unknown preservation state of the extrados of the and fragmentation of their compartments ААП3 Test sample D5 Absence of door arcade dome B10 Absence of access to the sea D6, D7, D8 Absence of window A8 Areas of the masonry which need additions B11 Areas of render showing decay



Installations E1 Unknown preservation state of the Agiasma supply

piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings




ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator



Whitish plaster			
Render of cement mortar			
Partial sealing with cement mortar			
Paint			Floors C1 Area below the recent floor which
Loss-erosion of render		Construction works	research C2 Recent floor of cement tiles which
Loss of pointing	 Structural problems A1 Area with problems of substratum differential settlement (see structural study) A2 Differential settlement of foundation (see structural study) A3 Area of the masonry showing cracks 	 B1 Poorly constructed cornice of cement mortar B2 Area with problems in draining rainwater B3 Absence of Altar B4 Poorly constructed cover plate of the well which leads to the underground galleries of the Agiasma 	higher than the original one C3 Problems of rising dampness C4 Recent floor of cement tiles which
Erosion of stone			C5 Poorly constructed floor of cemer C6 Stone floor in a bad preservation
Extensive erosion of stone		B5 Spring of the Agiasma showing traces of form alterations B6 Blocked window	concrete repairs C7 Poor repair of the steps with cem
Loss of stone	A4 Area of the masonry which needs solidification A5 Area of the masonry which needs conservation	B7 Surface of the masonry which needs conservation B8 Area where steps need to be constructed in order to	Joinery - doors & windows D1 Absence of icon screen
Crack	A6 Area of the extrados of the domes which needs consolidation	improve the transition from one level to the other B9 Stone steps showing local problems of detachments	D2 Absence of furniture of the Prothe D3 Existing masonry recess
AAIT3 Test sample	 A7 Unknown preservation state of the extrados of the arcade dome A8 Areas of the masonry which need additions 	and fragmentation of their compartments B10 Absence of access to the sea B11 Areas of render showing decay	D4 Timber 19th C doorway D5 Absence of door D6, D7, D8 Absence of window



ich needs excavational

nich was laid 10-15cm

nich needs replacement nent mortar ion state and with poor

ement mortar

othesis

Installations E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the

Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings




ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title:



Whitish plaster Render of cement mortar Partial sealing with cement mortar Floors Paint C1 Area below the recent floor which needs excavational research Loss-erosion C2 Recent floor of cement tiles which was laid 10-15cm Construction works of render higher than the original one **C3** Problems of rising dampness B1 Poorly constructed cornice of cement mortar Loss of pointing Structural problems B2 Area with problems in draining rainwater A1 Area with problems of substratum differential B3 Absence of Altar C4 Recent floor of cement tiles which needs replacement settlement B4 Poorly constructed cover plate of the well which leads C5 Poorly constructed floor of cement mortar Erosion of stone to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form C6 Stone floor in a bad preservation state and with poor (see structural study) A2 Differential settlement of foundation concrete repairs Extensive erosion of stone C7 Poor repair of the steps with cement mortar (see structural study) alterations B6 Blocked window A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification B7 Surface of the masonry which needs conservation Joinery - doors & windows Loss of stone A5 Area of the masonry which needs conservation **B8** Area where steps need to be constructed in order to D1 Absence of icon screen A6 Area of the extrados of the domes which needs **D2** Absence of furniture of the Prothesis improve the transition from one level to the other Crack D3 Existing masonry recess consolidation **B9** Stone steps showing local problems of detachments D4 Timber 19th C doorway A7 Unknown preservation state of the extrados of the and fragmentation of their compartments ААП3 Test sample arcade dome B10 Absence of access to the sea D5 Absence of door D6, D7, D8 Absence of window A8 Areas of the masonry which need additions B11 Areas of render showing decay



Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings




ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title:



Whitish plaster Render of cement mortar Partial sealing with cement mortar Floors Paint C1 Area below the recent floor which needs excavational research Loss-erosion Construction works of render higher than the original one **C3** Problems of rising dampness B1 Poorly constructed cornice of cement mortar Loss of pointing Structural problems B2 Area with problems in draining rainwater A1 Area with problems of substratum differential B3 Absence of Altar settlement B4 Poorly constructed cover plate of the well which leads Erosion of stone (see structural study) to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form A2 Differential settlement of foundation concrete repairs Extensive erosion of stone (see structural study) alterations B6 Blocked window A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification B7 Surface of the masonry which needs conservation Joinery - doors & windows Loss of stone A5 Area of the masonry which needs conservation **B8** Area where steps need to be constructed in order to D1 Absence of icon screen A6 Area of the extrados of the domes which needs improve the transition from one level to the other Crack D3 Existing masonry recess consolidation B9 Stone steps showing local problems of detachments D4 Timber 19th C doorway A7 Unknown preservation state of the extrados of the and fragmentation of their compartments ААП3 Test sample arcade dome B10 Absence of access to the sea D5 Absence of door D6, D7, D8 Absence of window A8 Areas of the masonry which need additions B11 Areas of render showing decay



C2 Recent floor of cement tiles which was laid 10-15cm C4 Recent floor of cement tiles which needs replacement C5 Poorly constructed floor of cement mortar

C6 Stone floor in a bad preservation state and with poor C7 Poor repair of the steps with cement mortar

D2 Absence of furniture of the Prothesis

KEY

Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

AI

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings



Implemented by the: In collaboration with the Technical Committee on Cultural Heritage

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: **SECTION 5-5** 1:50

Scale:	1:50
0	1
Date:	May 2007 Rev. February 2016
Plate number:	MCE08

Whitish plaster Render of cement mortar Partial sealing with cement mortar Paint Loss-erosion of render Loss of pointing Structural problems A1 Area with problems of substratum differential settlement Erosion of stone (see structural study) A2 Differential settlement of foundation Extensive erosion of stone (see structural study) A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification Loss of stone A5 Area of the masonry which needs conservation A6 Area of the extrados of the domes which needs Crack consolidation $\ensuremath{\text{A7}}$ Unknown preservation state of the extrados of the ААП3 Test sample arcade dome A8 Areas of the masonry which need additions

Construction works

B1 Poorly constructed cornice of cement mortar B2 Area with problems in draining rainwater

B3 Absence of Altar

B4 Poorly constructed cover plate of the well which leads

to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form

alterations B6 Blocked window

B7 Surface of the masonry which needs conservation B8 Area where steps need to be constructed in order to improve the transition from one level to the other B9 Stone steps showing local problems of detachments and fragmentation of their compartments B10 Absence of access to the sea


B11 Areas of render showing decay

Floors C1 Area below the recent floor which needs excavational research C2 Recent floor of cement tiles which was laid 10-15cm higher than the original one

C3 Problems of rising dampness C4 Recent floor of cement tiles which needs replacement C5 Poorly constructed floor of cement mortar C6 Stone floor in a bad preservation state and with poor

concrete repairs C7 Poor repair of the steps with cement mortar Joinery - doors & windows D1 Absence of icon screen

D2 Absence of furniture of the Prothesis D3 Existing masonry recess D4 Timber 19th C doorway D5 Absence of door D6, D7, D8 Absence of window



Installations E1 Unknown preservation state of the Agiasma supply

piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings




ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: **SECTION 6-6**



Whitish plaster Render of cement mortar Partial sealing with cement mortar Floors Paint C1 Area below the recent floor which needs excavational research Loss-erosion C2 Recent floor of cement tiles which was laid 10-15cm Construction works of render higher than the original one **C3** Problems of rising dampness B1 Poorly constructed cornice of cement mortar Loss of pointing Structural problems B2 Area with problems in draining rainwater A1 Area with problems of substratum differential B3 Absence of Altar C4 Recent floor of cement tiles which needs replacement settlement B4 Poorly constructed cover plate of the well which leads C5 Poorly constructed floor of cement mortar Erosion of stone to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form C6 Stone floor in a bad preservation state and with poor (see structural study) A2 Differential settlement of foundation concrete repairs Extensive erosion of stone C7 Poor repair of the steps with cement mortar (see structural study) alterations B6 Blocked window A3 Area of the masonry showing cracks A4 Area of the masonry which needs solidification B7 Surface of the masonry which needs conservation Joinery - doors & windows Loss of stone A5 Area of the masonry which needs conservation **B8** Area where steps need to be constructed in order to D1 Absence of icon screen A6 Area of the extrados of the domes which needs **D2** Absence of furniture of the Prothesis improve the transition from one level to the other Crack D3 Existing masonry recess consolidation B9 Stone steps showing local problems of detachments D4 Timber 19th C doorway A7 Unknown preservation state of the extrados of the and fragmentation of their compartments ААПЗ Test sample arcade dome B10 Absence of access to the sea D5 Absence of door D6, D7, D8 Absence of window A8 Areas of the masonry which need additions B11 Areas of render showing decay



Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings



Implemented by the: In collaboration with the Technical Committee on Cultural Heritage

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)




UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: **SECTION 7-7**

1:50 Scale: May 2007 Rev. February 2016 Date: Plate number: MCE10

<u>AN</u>






Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma

E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings



ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : Kalathas, civil engi G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: **SECTION 8-8** 1:50 Scale:

May 2007 Date: Rev. February 2016 Plate number: MCE1

Whitish plaster			
Render of cement mortar			
Partial sealing with cement mortar			
Paint			Floors C1 Area below the recent floor which
Loss-erosion of render		Construction works	research C2 Recent floor of cement tiles which higher than the original one
Loss of pointing	Structural problems A1 Area with problems of substratum differential	 B1 Poorly constructed cornice of cement mortar B2 Area with problems in draining rainwater B3 Absence of Altar 	C3 Problems of rising dampness C4 Recent floor of cement tiles which
Erosion of stone	settlement (see structural study)	B4 Poorly constructed cover plate of the well which leads to the underground galleries of the Agiasma	C5 Poorly constructed floor of cemer C6 Stone floor in a bad preservation
Extensive erosion of stone	A2 Differential settlement of foundation (see structural study) A3 Area of the masonry showing cracks	B5 Spring of the Agiasma showing traces of form alterations B6 Blocked window	concrete repairs C7 Poor repair of the steps with cem
Loss of stone	A4 Area of the masonry which needs solidification A5 Area of the masonry which needs conservation	B7 Surface of the masonry which needs conservationB8 Area where steps need to be constructed in order to	Joinery - doors & windows D1 Absence of icon screen
Crack	A6 Area of the extrados of the domes which needs consolidationA7 Unknown preservation state of the extrados of the	improve the transition from one level to the other B9 Stone steps showing local problems of detachments and fragmentation of their compartments	D2 Absence of furniture of the Prothe D3 Existing masonry recess D4 Timber 19th C doorway
AAIT3 Test sample	arcade dome A8 Areas of the masonry which need additions	B10 Absence of access to the sea B11 Areas of render showing decay	D5 Absence of door D6, D7, D8 Absence of window



ich needs excavational

nich was laid 10-15cm

hich needs replacement ment mortar tion state and with poor

ement mortar


othesis

Installations E1 Unknown pro

E1 Unknown preservation state of the Agiasma supply piping
E2 Water overflow in high locations of the arcades of the Agiasma
E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved
F2 Position of the cover plate of the well which needs excavational research
F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater
F4 Potential area for creating a new courtyard
F5 Recent parapet which has blocked the use of the descending staircase
F6 Absence of handrail
F7 Absence of railings



ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS


RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)




UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title:

SECTION 9-9 Scale: 1:50 0 1 Date: May 2007 Rev. February 2016 MCE12





Whitish plaster			
Render of cement mortar			
Partial sealing with cement mortar			
Paint			Floors C1 Area below the recent floor which
Loss-erosion of render		Construction works	research C2 Recent floor of cement tiles which higher than the original one
Loss of pointing	 Structural problems A1 Area with problems of substratum differential settlement (see structural study) A2 Differential settlement of foundation (see structural study) A3 Area of the masonry showing cracks 	 B1 Poorly constructed cornice of cement mortar B2 Area with problems in draining rainwater B3 Absence of Altar B4 Poorly constructed cover plate of the well which leads to the underground galleries of the Agiasma B5 Spring of the Agiasma showing traces of form alterations B6 Blocked window 	C3 Problems of rising dampness C4 Recent floor of cement tiles which
Erosion of stone			C5 Poorly constructed floor of cement C6 Stone floor in a bad preservation s
Extensive erosion of stone			concrete repairs C7 Poor repair of the steps with ceme
Loss of stone	A4 Area of the masonry which needs solidification A5 Area of the masonry which needs conservation	B7 Surface of the masonry which needs conservation B8 Area where steps need to be constructed in order to	Joinery - doors & windows D1 Absence of icon screen
Crack	A6 Area of the extrados of the domes which needs consolidation	improve the transition from one level to the other B9 Stone steps showing local problems of detachments	D2 Absence of furniture of the Prothes D3 Existing masonry recess
AAII3 Test sample	 A7 Unknown preservation state of the extrados of the arcade dome A8 Areas of the masonry which need additions 	and fragmentation of their compartments B10 Absence of access to the sea B11 Areas of render showing decay	D4 Timber 19th C doorway D5 Absence of door D6, D7, D8 Absence of window



ich needs excavational

ich was laid 10-15cm

ich needs replacement ent mortar on state and with poor

ment mortar


nesis


Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater **F4** Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings







ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title:

SECTION 10-10 1:50 Scale: May 2007 Rev. February 2016 Date: Plate number: MCE14

Whitish plaster Render of cement mortar Partial sealing with cement mortar Floors Paint C1 Area below the recent floor which needs excavational research Loss-erosion C2 Recent floor of cement tiles which was laid 10-15cm Construction works of render higher than the original one **C3** Problems of rising dampness B1 Poorly constructed cornice of cement mortar Loss of pointing Structural problems B2 Area with problems in draining rainwater A1 Area with problems of substratum differential B3 Absence of Altar C4 Recent floor of cement tiles which needs replacement settlement B4 Poorly constructed cover plate of the well which leads C5 Poorly constructed floor of cement mortar Erosion of stone to the underground galleries of the Agiasma **B5** Spring of the Agiasma showing traces of form (see structural study) C6 Stone floor in a bad preservation state and with poor A2 Differential settlement of foundation concrete repairs Extensive erosion of stone C7 Poor repair of the steps with cement mortar (see structural study) alterations A3 Area of the masonry showing cracks B6 Blocked window A4 Area of the masonry which needs solidification B7 Surface of the masonry which needs conservation Joinery - doors & windows Loss of stone A5 Area of the masonry which needs conservation **B8** Area where steps need to be constructed in order to D1 Absence of icon screen A6 Area of the extrados of the domes which needs **D2** Absence of furniture of the Prothesis improve the transition from one level to the other Crack D3 Existing masonry recess consolidation B9 Stone steps showing local problems of detachments D4 Timber 19th C doorway A7 Unknown preservation state of the extrados of the and fragmentation of their compartments ААПЗ Test sample arcade dome B10 Absence of access to the sea D5 Absence of door D6, D7, D8 Absence of window A8 Areas of the masonry which need additions B11 Areas of render showing decay




 \bigcirc XB8 **B8**

Installations

E1 Unknown preservation state of the Agiasma supply piping E2 Water overflow in high locations of the arcades of the Agiasma E3 Old timber electricity post

Other works

F1 Position of the old parapet with ashlar stone small piers which are not preserved F2 Position of the cover plate of the well which needs excavational research F3 osition of the old wall of the dock which has been covered by the rocks of the breakwater F4 Potential area for creating a new courtyard F5 Recent parapet which has blocked the use of the descending staircase F6 Absence of handrail F7 Absence of railings



RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

Implemented by the:


UNDP


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)





UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher : P.M. Koufopoulos, Assistant Professor Scientific advisors : S.V. Mamaloukos, Assistant Professor D.M.Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators : N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator EXISTING Title: SECTION 11-11

1:50 Scale: May 2007 Rev. February 2016 Date: Plate number: MCE15












SIDE VIEW





FRONT VIEW

DETAILS OF SPOUT




RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY PROJECT PHASE B:

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS



Implemented by the: UNDP In collaboration with the Technical Committee on Cultural Heritage





Structural reinforcements

A1 Location of the series of micropiles of 300mm diameter and length 10000mm-12000mm (MP1-MP30) A2a Support of the foundation with vertical rootpiles of 120mm diameter and 8000-10000mm length(RP1-RP16) A2b Inclined rootpiles at 45°, of 120mm diameter and 6000-8000mm length (RP5-RP16) A3 Stitching of the masonry cracks

A4 Consolidation of masonry with hydraulic limemortar (pointing)

A5 Conservation of masonry (stone replacement) A6 Consolidation of the external surfaces of the vaults with stiff hydraulic limemortar and carbon-fibre textile

A7 Cleaning and restoration of the external surfaces of

- vault (cleaning, grouting, stone consolidation) A8 Addition of stone masonry
- A9 Grouting with low pressure

A10 Grouting with quick set grout A11 Removal of rocks for pile execution and relocation

when the task is completed

General building construction works

B1 Reconstruction of cornice with dressed limestone (Limassol) (see P19)

- **B2** Demolish existing floor, place new concrete slab 150mm with a slight slope so as to drain rainwater **B3** Construction of the new Holy Altar (see P22)
- **B4** Removal of existing concrete caping of well. Construction of new SS & timber one
- B5 Restoration of fountain (Agiasma) (see P23)
- B6 Unblocking of a blocked window
- **B7** Conservation of the masonry surface
- B8 Construction of new steps with thick local stone
- **B9** Repair-restoration of existing steps
- B10 Gravel filling to form a horizontal level 5.45m B11 Restoration of rendering

Floors

C1 Removal of soil (excavation)

C2 Reconstruction of the floor at level

- C3 Construction of drainage system below the floor so as to reduce the rising dampness
- C4 New Limassol stone floor
- C5 New pebble floor with perimetric stone strips
- C6 Reconstruction of floor with irregular shaped stone

slabs (Limassol stone) C7 New glass floor (see MCP27)

- Joinery, doors & windows D1 Addition of new marble icon screen (see P21)
- D2 New door as existing one
- D3 New batten door
- D4 New glass window with SS frame D5 New SS grille

Installations

- E1 Laying of underfloor electrical power suppliers **E2** Reconstruction of piping supplying the Agiasma with
- stainless components E3 Lower overflow pipe by 30 cm
- E4 Removal of the old timber electrical post

Other works

F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well

- F3 New hand rail only (see MCP25)
- F4 New railing (see MCP25) F5 New railings to control the entrance

STRUCTURAL STUDY PROPOSAL

Root piles vertical and at 45° angle



- $\cdot \frac{1}{1}$ Carbon fibre in strips of three layers
- Removal of the filling material



Consolidation of the extrados of the domes



Implemented by the: UNDP In collaboration with the Technical Committee on Cultural Heritage


ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title:







6000-8000mm length (RP5-RP16) A3 Stitching of the masonry cracks A4 Consolidation of masonry with hydraulic limemortar (pointing) A5 Conservation of masonry (stone replacement) A6 Consolidation of the external surfaces of the vaults

- with stiff hydraulic limemortar and carbon-fibre textile A7 Cleaning and restoration of the external surfaces of
- vault (cleaning, grouting, stone consolidation)
- A8 Addition of stone masonry
- A9 Grouting with low pressure

A10 Grouting with quick set grout A11 Removal of rocks for pile execution and relocation when the task is completed

General building construction works

B1 Reconstruction of cornice with dressed limestone (Limassol) (see P19)

- **B2** Demolish existing floor, place new concrete slab
- 150mm with a slight slope so as to drain rainwater B3 Construction of the new Holy Altar (see P22)
- **B4** Removal of existing concrete caping of well. Construction of new SS & timber one
- B5 Restoration of fountain (Agiasma) (see P23)
- B6 Unblocking of a blocked window
- B7 Conservation of the masonry surface
- B8 Construction of new steps with thick local stone
- **B9** Repair-restoration of existing steps
- B10 Gravel filling to form a horizontal level 5.45m **B11** Restoration of rendering

Floors

- C1 Removal of soil (excavation)
- C2 Reconstruction of the floor at level
- C3 Construction of drainage system below the floor so as
- to reduce the rising dampness C4 New Limassol stone floor
- **C5** New pebble floor with perimetric stone strips
- C6 Reconstruction of floor with irregular shaped stone
- slabs (Limassol stone)
- C7 New glass floor (see MCP27)

Joinery, doors & windows

- D1 Addition of new marble icon so
- D2 New door as existing one
- D3 New batten door
- D4 New glass window with SS frame D5 New SS grille

Installations

- E1 Laying of underfloor electrical power suppliers
- E2 Reconstruction of piping supplying the Agiasma with
- stainless components
- E3 Lower overflow pipe by 30 cm E4 Removal of the old timber electrical post
- Other works F1 Reconstruction of parapet with small ashlar stone
- piers, metal railings and timber handrail (see P24)
- F2 New stone capping of well
- F3 New hand rail only (see MCP25)
- F4 New railing (see MCP25)
- **F5** New railings to control the entrance

STRUCTURAL STUDY PROPOSAL

Root piles vertical and at 45° angle

- ____ Stainless steel tie rod

- Removal of the filling material
 - Consolidation of the extrados of the domes



Implemented by the: UNDP n collaboration with the Technical Committee on Cultural Heritage


ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**


RESEARCH PROGRAMME FOR THE RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title:







Structural reinforcements

A1 Location of the series of micropiles of 300mm diameter and length 10000mm-12000mm (MP1-MP30) A2a Support of the foundation with vertical rootpiles of 120mm diameter and 8000-10000mm length(RP1-RP16) A2b Inclined rootpiles at 45°, of 120mm diameter and 6000-8000mm length (RP5-RP16)

A3 Stitching of the masonry cracks A4 Consolidation of masonry with hydraulic limemortar (pointing)

A5 Conservation of masonry (stone replacement) A6 Consolidation of the external surfaces of the vaults with stiff hydraulic limemortar and carbon-fibre textile

A7 Cleaning and restoration of the external surfaces of vault (cleaning, grouting, stone consolidation)

A8 Addition of stone masonry

A9 Grouting with low pressure A10 Grouting with quick set grout

A11 Removal of rocks for pile execution and relocation when the task is completed

General building construction works

B1 Reconstruction of cornice with dressed limestone (Limassol) (see P19)

B2 Demolish existing floor, place new concrete slab 150mm with a slight slope so as to drain rainwater

- **B3** Construction of the new Holy Altar (see P22)
- B4 Removal of existing concrete caping of well.
- Construction of new SS & timber one
- B5 Restoration of fountain (Agiasma) (see P23)
- B6 Unblocking of a blocked window
- B7 Conservation of the masonry surface
- B8 Construction of new steps with thick local stone
- **B9** Repair-restoration of existing steps B10 Gravel filling to form a horizontal level 5.45m
- B11 Restoration of rendering

Floors

- C1 Removal of soil (excavation)
- C2 Reconstruction of the floor at level
- C3 Construction of drainage system below the floor so as
- to reduce the rising dampness
- C4 New Limassol stone floor

C5 New pebble floor with perimetric stone strips C6 Reconstruction of floor with irregular shaped stone

slabs (Limassol stone) C7 New glass floor (see MCP27)

Joinery, doors & windows **D1** Addition of new marble icon screen (see P21)

D2 New door as existing one

D3 New batten door D4 New glass window with SS frame D5 New SS grille

Installations

E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with stainless components E3 Lower overflow pipe by 30 cm E4 Removal of the old timber electrical post

Other works

F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25) F5 New railings to control the entrance



Root piles vertical and at 45° angle

____ Stainless steel tie rod



 $- \cdot \frac{1}{1} \cdot - \frac{1}{1}$ Carbon fibre in strips of three layers

Removal of the filling material

Consolidation of the extrados of the domes



Implemented by the: UNDP n collaboration with the Technical Committee on Cultural Heritage


ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title: PLAN OF LEVEL B'









A1 Location of the series of micropiles of 300mm diameter and length 10000mm-12000mm (MP1-MP30) A2a Support of the foundation with vertical rootpiles of 120mm diameter and 8000-10000mm length(RP1-RP16) A2b Inclined rootpiles at 45°, of 120mm diameter and 6000-8000mm length (RP5-RP16)

A3 Stitching of the masonry cracks A4 Consolidation of masonry with hydraulic limemortar (pointing)

A5 Conservation of masonry (stone replacement) A6 Consolidation of the external surfaces of the vaults with stiff hydraulic limemortar and carbon-fibre textile A7 Cleaning and restoration of the external surfaces of vault (cleaning, grouting, stone consolidation)

A8 Addition of stone masonry

A9 Grouting with low pressure A10 Grouting with quick set grout

A11 Removal of rocks for pile execution and relocation when the task is completed

General building construction works

B1 Reconstruction of cornice with dressed limestone (Limassol) (see P19) B2 Demolish existing floor, place new concrete slab 150mm with a slight slope so as to drain rainwater B3 Construction of the new Holy Altar (see P22) **B4** Removal of existing concrete caping of well. Construction of new SS & timber one **B5** Restoration of fountain (Agiasma) (see P23) **B6** Unblocking of a blocked window B7 Conservation of the masonry surface B8 Construction of new steps with thick local stone **B9** Repair-restoration of existing steps B10 Gravel filling to form a horizontal level 5.45m **B11** Restoration of rendering Floors C1 Removal of soil (excavation)

- C2 Reconstruction of the floor at level
- C3 Construction of drainage system below the floor so as
- to reduce the rising dampness
- C4 New Limassol stone floor

C5 New pebble floor with perimetric stone strips

C6 Reconstruction of floor with irregular shaped stone

slabs (Limassol stone) C7 New glass floor (see MCP27)

Joinery, doors & windows

- D1 Addition of new marble icon s
- D2 New door as existing one D3 New batten door
- D4 New glass window with SS frame
- D5 New SS grille

Installations

E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with

- stainless components
- E3 Lower overflow pipe by 30 cm
- E4 Removal of the old timber electrical post


Other works


- F1 Reconstruction of parapet with small ashlar stone
- piers, metal railings and timber handrail (see P24) F2 New stone capping of well
- F3 New hand rail only (see MCP25)
- F4 New railing (see MCP25)
- F5 New railings to control the entrance



Root piles vertical and at 45° angle

- ____ Stainless steel tie rod
- $\cdot \frac{1}{1} \cdot \frac{1}{1}$ Carbon fibre in strips of three layers







UNDP In collaboration with the Technical Committee on Cultural Heritage

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS


RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title: PLAN OF LEVEL C 1:50 Scale:

April 2006 Date: Rev. February 2016 MCP04 Plate number:





Sea level





ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**


> RESEARCH PROGRAMME FOR THE AND RECONFIGURATION OF THE

RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)







Installations

Installations
E1 Laying of underfloor electrical power suppliers
E2 Reconstruction of piping supplying the Agiasma with
stainless components
E3 Lower overflow pipe by 30 cm
E4 Removal of the old timber electrical post

Other works

F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25) F5 New railings to control the entrance



ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX


AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator т:н.

l itie:	PROPOSAL
SE	CTION 2-2
Scale:	1:50
0	1
Date:	April 2006
	Rev. February 2016
Plate number:	MCP07





Installations

E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with stainless components E3 Lower overflow pipe by 30 cm E4 Removal of the old timber electrical post

Other works

F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25)

F5 New railings to control the entrance



ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)





UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title: **SECTION 3-3**

1:50 April 2006 Date: Rev. February 2016 MCP08 Plate number:

Scale







OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**

RESEARCH PROGRAMME FOR THE

RESTORATION AND REHABILITATION OF THE HISTORIC BUILDING COMPLEX

AND RECONFIGURATION OF THE

ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION

MEDIEVAL CHAPEL (MC)

UNIVERSITY OF PATRAS

SCHOOL OF ENGINEERING

DEPARTMENT OF ARCHITECTURE

LABORATORY OF URBAN

AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer

M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer

G. Demetriades, civil engineer

O. Monogios, electrical engineer L. Vacanas, mechanical engineer


ADMINISTRATIVE COMMITEE

Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title: **SECTION 4-4** 1:50

April 2006 Date: Rev. February 2016 MCP09

Plate number:

Scale:



E4 Removal of the old timber electrical post Other works F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25) F5 New railings to control the entrance

E1 Laying of underfloor electrical power suppliers

E2 Reconstruction of piping supplying the Agiasma with

Installations

stainless components

E3 Lower overflow pipe by 30 cm




ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title:



KEY				Structural reinforcements A1 Location of the series of micropiles of 300 diameter and length 10000mm-12000mm (MI A2a Support of the foundation with vertical ro
Existing structures	5		STRUCTURAL STUDY	120mm diameter and 8000-10000mm length(A2b Inclined rootpiles at 45°, of 120mm diam
Proposed structur	es	Conservation of render	PROPOSAL	6000-8000mm length (RP5-RP16) A3 Stitching of the masonry cracks
New cast pebbled	floor	Demolition of render	Root piles vertical and at 45° angle	A4 Consolidation of masonry with hydraulic lin (pointing)
Stone strips		Cast stone (mortar) repair	Stainless steel tie rod	 A5 Conservation of masonry (stone replacem A6 Consolidation of the external surfaces of t with stiff hydraulic limemortar and carbon-fibro
Removal of ceme	nt-based render	Stone replacement	$- \cdot \frac{1}{1} \cdot -$ Carbon fibre in strips of three layers	A7 Cleaning and restoration of the external so vault (cleaning, grouting, stone consolidation)
Repair of existing	render/ new render	Crack	Removal of the filling material	A8 Addition of stone masonryA9 Grouting with low pressureA10 Grouting with quick set grout
Pointing		Gravel back filling	Consolidation of the extrados of the domes	A11 Removal of rocks for pile execution and when the task is completed



0mm (P1-MP30) rootpiles of h(RP1-RP16) meter and

imemortar

ent)

the vaults ore textile urfaces of

relocation

General building construction works

B1 Reconstruction of cornice with dressed limestone (Limassol) (see P19)

B2 Demolish existing floor, place new concrete slab 150mm with a slight slope so as to drain rainwater B3 Construction of the new Holy Altar (see P22)

- B4 Removal of existing concrete caping of well. Construction of new SS & timber one
- B5 Restoration of fountain (Agiasma) (see P23) B6 Unblocking of a blocked window B7 Conservation of the masonry surface
- B8 Construction of new steps with thick local stone
- **B9** Repair-restoration of existing steps B10 Gravel filling to form a horizontal level 5.45m
- **B11** Restoration of rendering

Floors

- C1 Removal of soil (excavation)
- C2 Reconstruction of the floor at level C3 Construction of drainage system below the floor so as
- to reduce the rising dampness C4 New Limassol stone floor
- **C5** New pebble floor with perimetric stone strips
- C6 Reconstruction of floor with irregular shaped stone slabs (Limassol stone) C7 New glass floor (see MCP27)

Joinery, doors & windows D1 Addition of new marble icon screen (see P21) D2 New door as existing one D3 New batten door D4 New glass window with SS frame D5 New SS grille

- Installations
- E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with
- stainless components E3 Lower overflow pipe by 30 cm
- E4 Removal of the old timber electrical post

Other works


F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25)

F5 New railings to control the entrance




In collaboration with the Technical Committee on Cultural Heritage


ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS



PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)

SCHOOL OF	Y OF PATRAS ENGINEERING	
DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING		
Director : Professor N.D. Polydorides		
Main Researcher: P. M. Koufopoulos, Assistant Professor		
Scientific advisors:		
S.V. Mamaloukos, Assistant Professor		
D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer		
Collaborators:		
N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator		
Title:	PROPOSAL	
SECTION 6-6		
Scale:	1:50	
0	1	
Date:	April 2006	
_	Rev. February 2016	
Plate number:		





B9 Repair-restoration of existing steps

B11 Restoration of rendering

B10 Gravel filling to form a horizontal level 5.45m


Installations

E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with stainless components E3 Lower overflow pipe by 30 cm

E4 Removal of the old timber electrical post

Other works

F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25) F5 New railings to control the entrance





ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS


RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title: SECTION 7-7 & EXTERNAL FLOOR DETAIL Scale: 1:50, 1:20 & 1:10

0	1
Date:	April 2006
	Rev. February 2016
Plate number:	MCP12





OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS


RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title:

SECTION 8-8 1:50 Scale April 2006 Date Rev. February 2016 Plate number:





Installations

E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with stainless components E3 Lower overflow pipe by 30 cm E4 Removal of the old timber electrical post

Other works

F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25)

F5 New railings to control the entrance



Implemented by the: In collaboration with the Technical Committee on Cultural Heritage

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY


PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)




UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title: **SECTION 9-9** 1:50

0	1
Date:	April 2006 Rev. February 2016
Plate number:	MCP14

Scale





Installations

E1 Laying of underfloor electrical power suppliers E2 Reconstruction of piping supplying the Agiasma with stainless components E3 Lower overflow pipe by 30 cm E4 Removal of the old timber electrical post

Other works


F1 Reconstruction of parapet with small ashlar stone piers, metal railings and timber handrail (see P24) F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25) F5 New railings to control the entrance




ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



PROPOSAL Title: SECTION 10-10 1:50 Scale: April 2006 Date: Rev. February 2016 Plate number: MCP16





Implemented by the: UNDP In collaboration with the Technical Committee on Cultural Heritage


ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS **RIZOKARPASSO, CYPRUS**

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)














In collaboration with the Technical Committee on Cultural Heritage

50














In collaboration with the Technical Committee on Cultural Heritage













DETAILS OF SPOUT A-TYPE

FRONT VIEW











FRONT VIEW


DETAILS OF SPOUT A-TYPE



























ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

> RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION**

OF THE HISTORIC BUILDING COMPLEX

AND RECONFIGURATION OF THE

ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION

MEDIEVAL CHAPEL (MC)

UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE

LABORATORY OF URBAN

AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor

Scientific advisors:

S.V. Mamaloukos, Assistant Professor

D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer

Collaborators:


N. Kalathas, civil engineer G. Demetriades, civil engineer





 O. Monogios, electrical engineer
 L. Vacanas, mechanical engineer
 Ch. Makris, quantity surveyor
 G. Dogani, antiquities conservator A. Galanou, antiquities conservator PROPOSAL Title:


DETAIL of Holy Altar Scale: 1:20, 1:2


Date: April 2006 Rev. February 2016 Plate number: April 2006




















ELEVATION









INDICATIVE PLACING OF RAILING SC. 1:20


B-TYPE HANDRAIL







Implemented by the: UNDP In collaboration with the Technical Committee on Cultural Heritage



Installations E1 Laying of underfloor electrical power supplier E2 Reconstruction of piping supplying the Agiası stainless components E3 Lower overflow pipe by 30 cm E4 Removal of the old timber electrical post

ashlar stor (see P24) Other works F1 Reconstruction of parapet with small as piers, metal railings and timber handrail (st F2 New stone capping of well F3 New hand rail only (see MCP25) F4 New railing (see MCP25) F5 New railings to control the entrance

EXTERNAL FLOORS 1:75

ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY

OF APOSTOLOS ANDREAS

RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE

RESTORATION AND REHABILITATION

OF THE HISTORIC BUILDING COMPLEX

AND RECONFIGURATION OF THE


ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION


MEDIEVAL CHAPEL (MC)




Implemented by the: UNDP In collaboration with the Technical Committee on Cultural Heritage









Milas limon marble slabs Lime-cement mortar

Concrete slab 10 cm

D2: MEDIEVAL CHURCH INTERNAL FLOOR 1:5

D5 MONOLITHIC STEPS DETAIL 1:5



ADMINISTRATIVE COMMITEE OF THE HOLY MONASTERY OF APOSTOLOS ANDREAS RIZOKARPASSO, CYPRUS

RESEARCH PROGRAMME FOR THE **RESTORATION AND REHABILITATION** OF THE HISTORIC BUILDING COMPLEX AND RECONFIGURATION OF THE ENVIRONMENT OF THE MONASTERY

PROJECT PHASE B: IMPLEMENTATION MEDIEVAL CHAPEL (MC)



UNIVERSITY OF PATRAS SCHOOL OF ENGINEERING DEPARTMENT OF ARCHITECTURE LABORATORY OF URBAN AND REGIONAL PLANNING Director : Professor N.D. Polydorides Main Researcher: P. M. Koufopoulos, Assistant Professor Scientific advisors: S.V. Mamaloukos, Assistant Professor D.M. Myrianthefs, architect-restorer M.M. Myriantheos, architect-restorer Collaborators: N. Kalathas, civil engineer G. Demetriades, civil engineer O. Monogios, electrical engineer L. Vacanas, mechanical engineer Ch. Makris, quantity surveyor G. Dogani, antiquities conservator

PROPOSAL Title: DRAINAGE & OTHER DETAILS

Scale:

A. Galanou, antiquities conservator

1:5



