

Scope of Work


Background

The Stabilization Facility for Libya aims to bridge the critical period of transition from initial period of humanitarian relief towards mid- and long-term structural and sector-specific support. It includes time bound quick interventions at the municipality level providing concrete improvements and peace dividends at the community level through rehabilitation of critical infrastructure, building the capacity of local authorities and enhancing local mediation and conflict resolution capacities and processes.

Under this project, UNDP Libya is working to repair light infrastructure within the conflict affected areas to reverse the physical disruption caused by the conflict and enable the reopening of key services at the municipal level. It will also support quick recovery of businesses that are critical to the survival of whole communities through rehabilitation and provision of equipment. Through these activities it will also aim to boost the capacity of municipalities.

Institute Description


The Building institute is located in the residential Area No3 in the city of Sirte which had suffered a fighting during the last war, which led to a wide destruction in this area, and Institute had suffered some of this destruction.



This institute consists of few departments of different areas on total area of 11520 m2, divided into two floors, the total area of roof is 754 m2.

The ground floor is containing the administration labs, restrooms, and contain the classrooms, the first floor is containing offices, class rooms, and the studying interval is in the morning with 60 students are enrolled.

The sketch plan is showing the internal details of this building



The institute was built in 1997, and last maintained and rehabilitated comprehensively in 2003.

Required work

The institute requires rehabilitation mainly in the broken glass of windows and doors, as well as the repairing of those windows and doors as detailed in the draft BOQ.

Some openings in the walls of the institute has resulted from the conflict and its shown in the accompanied photos in this report. The rooms' doors need the repairing of the locks and some needs handles as well, so as some windows in the facility as shown in pictures and BOQ.







