

Scope of Work

Background

The Stabilization Facility for Libya aims to bridge the critical period of transition from initial period of humanitarian relief towards mid- and long-term structural and sector-specific support. It includes time bound quick interventions at the municipality level providing concrete improvements and peace dividends at the community level through rehabilitation of critical infrastructure, building the capacity of local authorities and enhancing local mediation and conflict resolution capacities and processes.

Under this project, UNDP will repair light infrastructure within the conflict affected areas to reverse the physical disruption caused by the conflict and enable the reopening of key services at the municipal level. It will also support quick recovery of businesses that are critical to the survival of whole communities through rehabilitation and provision of equipment. Through these activities it will also aim to boost the capacity of municipalities.

Facility description

The Alrebaat “Aljeeza” HCU is in the residential area of Aljeeza in the eastern side of the city of Sirte which had suffered a fighting during the last war, which led to a wide destruction in this area, and Institute had suffered some of this destruction.




This clinic consists of few departments of different areas on total area of the clinic of 891 m2, with one floor, the total area of roof is 247 m2.

The clinic is containing of: -

- 5 rooms as outpatient clinic the administration offices;
- One dental room;
- Internal Medicine Room;
- Pharmacy;
- Administrations Department: consists of one room;
- One kitchen; and
- One bath room.

The sketch plan is showing the internal details of this building



The HCU was built in 2007, and last maintained and rehabilitated comprehensively in 2013.

Required work

The HCU requires rehabilitation mainly in the broken glass of windows and doors, as well as the repairing of those windows and doors as detailed in the draft BOQ.

Some openings in the walls of the HCU has resulted from the conflict and its shown in the accompanied photos in this report. The rooms' doors need the repairing of the locks and some needs handles as well, so as some windows in the HCU as shown in pictures and BOQ.





