

Considerando que se trata de um edificio em advancado estado de degradacao, na inspecao visual constatamos a existencia de muit vegatcao, deposito de lixos. Mas em termos de avaliacao da resistencia mecanica do pavimento e das paredes divoria ensaidas contatamos que eles apresentam em media a resistencia mecanica aceitaveis para o tipo de obra a ser implantada. No pavimentos obtivemos uma resistencia mecanica media aproximadamente 17 n/mm<sup>2</sup> enquanto que nas paredes divisorias a media aproximada e de 19 n.mm<sup>2</sup>.

Em suma podemos concluir que as partes ensaiadas podem ser aproveitadas neste trabalho de rehabilitacao.

---

Considering that it is a building in an advanced state of degradation, in the visual inspection we find the existence of much vegetation, deposit of garbage. But in terms of the evaluation of the mechanical resistance of the floor and of the walls, we have contacted that they present on average the mechanical resistance acceptable to the type of work to be implanted. In the pavements we obtained a mechanical resistance of approximately 17 n / mm<sup>2</sup>, while in the partition walls the average was approximately 19 n.mm<sup>2</sup>.

In sum we conclude that the **parts tested** can be used in this rehabilitation work.