


**UNDP CYP RFQ 113 2019 - Conservation and improvement works at Panagia Evangelistria Church**

**Clarifications no: 1 dated 26 November 2019**

Q1.	<p>We have not been able to prepare a quotation due to lack of information such as dimensions in the drawings given in the terms of reference. For instance, the bidder is expected to evaluate cost of replacing the corroded iron elements with the same size iron elements. However, specifications and/or dimensions of either the existing or the new elements are not given. As the bell tower is a high structure, we have not had the opportunity to visually inspect and take measurements either.</p> <p>We will appreciate if the unclear points in the design are clarified so that a healthy evaluation can be done which will lead to a realistic quotation.</p>	<p>Iron clamps found in the bellow will be repaired and placed as per the description of works.</p> <p>For an idea of the dimensions of the iron clamps in the bellow please refer to the sketches (sketch no:1 and no:2 are already in Annex 1. Page 1.)</p> <p>Sketch number 3 is an additional sketch. Please refer to revision no:1 dated 26 November 2019.</p>
	<b>Sketch no:1</b>	
		
	<b>Sketch no:2</b>	
	