

Bid Bulletin 01

IRQ-RFQ-171-21

**Rehabilitation of Roof of the Environmental College Mosul University
-East Mosul-Ninawa Governorate Iraq. GPS: E 36.3851004, N
43.1405604**

**Please use the locked Excel version BOQ (Mandatory) and submit
both (signed and stamped PDF version and the locked Excel
version) with your offers**

**Please note that submitting an Unlocked Excel BOQ may lead to your
disqualification**

Questions	Answers
In the case of an AC (outdoor part)not working on the roof pr, is the company obligated to repair this AC?	As mentioned in the BoQ all Ac unit All (Mechanical, electrical) Systems should be removed temporarily, water tanks, pipes, fittings, and any obstruction from the roof of the building and reinstalling as existing with compensation for any missing or damaged part after completed works, ready to be used