




Front side elevation of the watch tower
(outside the compound view)






Ground floor of Villa No. 9




Internal plan view after implementation status of the boundary wall with the two watch towers




Modification process of New 9 Villas of UNCC
Garowe in Puntland state of Somalia




Modification process of the boundary wall




North side elevation of the security room and toilet of UNCC Garowe.




Current North side elevation of the temporary kitchen and cleaner ladies resting room of UNCC Garowe.




After implementation North side elevation of the temporary kitchen and cleaner ladies resting room of UNCC Garowe.



Over roof floor of the new 8 villas



After implementation plan view of the temporary kitchen and cleaner ladies resting room of UNCC Garowe.



Plan view of the security room and toilet of UNCC Garowe.