

PRE-BID MEETING MINUTES

RFQ-028/18 Hammam Rehabilitation	Date of Pre	-bid Meeting	21.01.2018		
Location of Pre-Bid Meeting: Hammam Al Alil Sub District- Mosul District- Ninawa Government					
Date/Ti	Name (a) and ich title of HADD Day				
Start	End	Name(s) and job title of UNDP Rep.			
10:00 AM	01:00 PM	Alaa Yaseen Rashid Consultant Civil Engineer			

	RECORD OF ATTENDANCE						
No:	Name	Position	Company or Agency	Mobile/E-mail			
1	Ahmed Mudhafar	Site Engineer	Berat Company	Karzan.yaseen@berat-			
				<u>ltd.com</u>			
				07702061187			
2	Marwan Abul	Site Engineer	Razawan Company	razawanco@gmail.com			
	Wahhab			07706127885			

QUESTIONS AND ANSWERS

Item No:	BIDDER QUESTIONS ASKED	UNDP RESPONSES GIVEN
1	What about the existing damaged	All damaged benches should be removed as
	benches, should we remove it?	part of site preparation item.
2	One missing gate in the Al Waleed Roundabout and required to repair?	End user will bring back this gate and install it to be repaired by the contractor.
3	Security of the site required, can End user support us for this issue?	No, Security during the implementation period is contractor responsibility, contractor should submit security plan before start to proceed accordingly.

Certification of Minutes as a true record of the proceedings of the meeting/site visit: Prepared by:

Signature:

Name:

Position:

Date: 21.01.2018

Alaa Yaseen Rashid

Consultant Civil Engineer

Site Visit Report



#	RFQ-028/18 - Ha 3 Roundabouts P Rehabilitation		Date of Site Visit	21.01.2018	Escorted by Military forces?			Yes No
	Time of S	ite Visit End	Nar	me(s) and job ti	tle of Gov. Re	р.		
	10:00 AM	1:00 PM	130.	جم لرحن مار	pul	}	Hamman	ality Survoya
#	Names of comp	anies attended	Rep. n	ame		Mot	ile/Email	Signature
1	Beratcom	Rny	Ahm	ed Mudhafar	no benit-	140	02061187	2-1-
2	Razewan	Compan	Mar	WanAbed	dalwahab @ amail	07	70 G1278	85 g
3		1						
4				r design afficients of the the relative relative				5 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1
5								
6								
7								
8								50 14 15 15 15 15 15 15 15 15 15 15 15 15 15
9								
10								
11								
12								
13								
14		magum g sa	/					
15								
16		1						
17						/		
20					/			
21				VI				

		- 500 (4 × 45 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
Questions Asked By Contractors				
#	Question ?	UNDP Respond		
1	What about theexisting damaged barches?	all damaged blencher shows as Part of Site Prefamile This door Enduser Promise		
2	What about Theexisting damaged barches? One missing door missin Almalid Park?	this door Enduser Promiso to bring it Back.		
3	What about The Security during The work time?	Contractor responsibility		
4		Sur 19 Impression		
5				
6				
7				
8				
9				
10				

Notes:

Prepared by:		
Q. K		
Signature:	Name:	Eng. Alaa Yaseen
Position: Consultant Civil Engineer	Date:	21.01.2018