

July 26, 2018

ADDENDUM 01

RFQ 540/18 - Rehabilitation of Sinjar Water Directorate-Sinjar District-Ninawa Governorate Site Visit

Following clarifications were sought. Please see the responses

Item No.	Bidders Questions	UNDP Response
		As per our BoQ in item (no.5) the bidder
		should Supply of materials, tools and manpower to
5. Civil works -	How to solve roof leaking?	repair wall cracks and remove the damaged cement
		plastering of external walls & fence by removing
		the damaged cement plastering minimum 35cm at
		each side of the crack, then treat the cracks with
		crack filler approved by manufacture with cement
		mortar 1:3 and using SBR at a rate of 200gr per m2,
		later putting a layer of metal chicken mesh 10 cm
		overlap each side on the area with 3 layers of
		cement plastering 1:3. All needed works to
		complete the job, will be included within the price.
8 Civil works - Gypsum		
plastering with crack		i. Cracked cement plastering will be solved as
repairing		clarified below:
	How to repair cracks?	Supply of materials, tools and manpower to
		repair wall cracks and remove the damaged cement
		plastering of external walls & fence by removing
		the damaged cement plastering minimum 35cm at
9. Civil works		each side of the crack, then treat the cracks with
		crack filler approved by manufacture with cement
		mortar 1:3 and using SBR at a rate of 200gr per m2,

cement plastering 1:3. All needed works to complete the job, will be included within the price.(as per item no.9) ii. Cracked Gypsum Plastering will be so as clarified below: Supply of all necessary materials, tools a manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minit thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsum plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the	Cement plastering with	later putting a layer of metal chicken mesh 10 cm
complete the job, will be included within the price.(as per item no.9) ii. Cracked Gypsum Plastering will be so as clarified below: Supply of all necessary materials, tools a manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minit thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsum plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the	crack repairing	overlap each side on the area with 3 layers of
ii. Cracked Gypsum Plastering will be so as clarified below: Supply of all necessary materials, tools a manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minithickness 20mm. The work includes repairing wall cracks by removing the damaged gypsuplastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		cement plastering 1:3. All needed works to
ii. Cracked Gypsum Plastering will be so as clarified below: Supply of all necessary materials, tools a manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minit thickness 20mm. The work includes repairin wall cracks by removing the damaged gypsu plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		complete the job, will be included within the
as clarified below: Supply of all necessary materials, tools a manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minit thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsum plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		price.(as per item no.9)
Supply of all necessary materials, tools a manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minimulated thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsum plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		ii. Cracked Gypsum Plastering will be solved
manpower to remove the damaged gypsum plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers minimum thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsum plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		as clarified below:
plastering of internal walls & ceiling and pla with new gypsum plastering in 2 layers mini thickness 20mm. The work includes repairin wall cracks by removing the damaged gypsu plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		Supply of all necessary materials, tools and
with new gypsum plastering in 2 layers minimulation thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsum plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		manpower to remove the damaged gypsum
thickness 20mm. The work includes repairing wall cracks by removing the damaged gypsut plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		plastering of internal walls & ceiling and plastering
wall cracks by removing the damaged gypsu plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		with new gypsum plastering in 2 layers minimum
plastering 25cm at each side of the crack, the filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		thickness 20mm. The work includes repairing of
filling the cracks with cement mortar 1:3 and SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		wall cracks by removing the damaged gypsum
SBR at a rate of 200gr per m2, later putting a of plastic mesh on the area under the gypsum plastering. All needed works to complete the		plastering 25cm at each side of the crack, then
of plastic mesh on the area under the gypsum plastering. All needed works to complete the		filling the cracks with cement mortar 1:3 and using
plastering. All needed works to complete the		SBR at a rate of 200gr per m2, later putting a layer
		of plastic mesh on the area under the gypsum
will be included within the price (as per item		plastering. All needed works to complete the job,
with the included within the price. (as per item		will be included within the price. (as per item no.8)

This Addendum -01 forms an integral part of the RFQ-540/18. All other Terms and Conditions in this RFQ will remain unchanged.

Piero Emanuele Franceschetti
Head of Service Center, UNDP, Iraq