



August 20th, 2018

ITB-598- 18- REHABILITATION OF ITIMARAT TAHTANY SCHOOL IN TALAFAR-NINAWA

GOVERNORATE

SITE VISIT QUESTIONS AND ANSWERS

Description/ Nº Item	QUESTION	UNDP RESPONSE
Civil Works - Item #5 (Repairing of roofing system)	What are the levels of roofing?	The same old levels that lead to the roof drains.
Civil Works - Item #12 (Cement Plastering without crack repairing) and Item #15 (Plastic painting)	How to repair walks?	Remove the old plain concrete and cast plain concrete thickness 10 cm and then repair the damaged cement plastering and paint with plastic paint.
Sanitary Works - Item #12 (Galvanized iron water pipes(1"))	How to supply school with Water?	The water has to be supplied from the main village's water tank, which is about 700 meters away, by a galvanized iron water pipes 1-inch diameter.