



Empowered lives.  
Resilient nations.

April 11<sup>th</sup>, 2019

**ADDENDUM 02**

**ITB 099/19 - Rehabilitation of Blood Bank Building in Al Shifaa Hospital Complex-West Mosul-Ninawa Governorate**

Following clarifications were sought. Please see the responses

**Question via email**

Item	Bidders Questions	UNDP Response
1	<p>Kindly note that the required refrigerant gas for screw chillers is R407c or R410a, noting that these types of refrigerants are not applicable with screw chillers.</p> <p>Please confirm use <b>R134a refrigerant</b> instead of above.</p>	<p><b>UNDP confirms that the required refrigerant gas is R134a as indicated in the BOQ.</b></p> <p><b>The Mechanical Compliance Sheet has been revised to reflect this .</b></p>

This Addendum -02 forms an integral part of the RFQ-099/19 All other Terms and Conditions in this ITB will remain unchanged.

Yours sincerely,

  
**Piero Emanuele Franceschetti**

Head of Service Center, UNDP, Iraq