(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawes	i	KABUPATEN Kota P		Palu	KECAMATAN	Tata	anga
SCHOOL FACILITY? Yes GoI Facility name		SD Negeri 21 Palu							
HEALTH FACILITY Gol Facilit			Gol Facility na	me					
Street Address Jl. Delima No.3, Kel. Boyaoge				Postco	de	94223			

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/		No
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment		•	
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri 21 PALU
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 54′ 28.793″ S	0° 54′ 28.793″ S 119° 51′ 16.074″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT			
BUDGET NEEDED IN RENAKSI (IDR)	N/A							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri 21 Palu should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Kota P		Palu	KECAI	MATAN	Tatanga	
SCHOOL FACILITY? Yes GoI Facility name			SD Negeri Peng	awu	<u>i</u>					
HEALTH FAC	HEALTH FACILITY			Gol Facility na	me					
Street Address Jl. Malontara no. 10, Kel. Pengawu			<u>i</u>		Postcod	le 942	.39			

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ²	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/		No
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
•••••	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?	•	
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and
 diligent in producing a "360° assessment of each site (a) National, Provincial and community stakeholders have provided initial
 consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c)
 consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri PENGAWU
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 55′ 22.519″ S	0° 55′ 22.519″ S 119° 50′ 49.924″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT			
BUDGET NEEDED IN RENAKSI (IDR)	3,220,310,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri Pengawu should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE Central Sulawesi		KABUPATEN Kota Palu		KECAMATAN	Palu Timur
SCHOOL FACILITY?	Yes	Gol Facility name SMP Negeri 14 Palu		4 Palu	
HEALTH FACILITY		Gol Facility nam	1е		
Street Address Jl. Letjen Suprapto no. 67				Postco	de 94111

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ³	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
•••••	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?	•	
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMP Negeri 14 PALU
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 53′ 21.826″ S	0° 53′ 21.826″ S 119° 52′ 31.127″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT			
BUDGET NEEDED IN RENAKSI (IDR)	4,070,256,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMP Negeri 14 Palu should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawes	si	KABUPATEN Kota P		Palu	KECAMA	TAN M a	antikulore
SCHOOL FACILITY? Yes			Gol Facility name SMK Negeri 8 Palu						
HEALTH FAC	HEALTH FACILITY			Gol Facility na	me				
Street Address Jl. Ragigau no			.3 Palu				Postcode	94228	

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ⁴	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?	Yes	
		Enlargement or realignment of site boundaries required?	Yes	
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment		•	
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and
 diligent in producing a "360° assessment of each site (a) National, Provincial and community stakeholders have provided initial
 consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c)
 consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMK Negeri 8 PALU
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 52′ 16.561″ S 119° 53′ 25.271″ E						
Damage Severity	HEAVY	X	MODERATE		LIGHT		
BUDGET IN RENAKSI (IDR)	5,506,560,000						

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMK Negeri 8 Palu should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN	Sigi		KECAMATAN	Sig	i Biromaru
SCHOOL FA	CILITY?	Yes		Gol Facility na	me	SD Inpres Jono Oge			
HEALTH FAC	CILITY			Gol Facility na	me				
Street Addr	ess	Jl. Las	oso, De	sa Jono Oge			Postc	ode	94364

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ⁵	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?	•	No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Inpres JONO OGE
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 58′ 53.162″ S	0° 58′ 53.162″ S 119° 54′ 58.158″ E						
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT						
BUDGET NEEDED IN RENAKSI (IDR)	1,226,384,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Inpres Jono Oge should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Sigi		KECAMATAN	Sigi Biromaru	
SCHOOL FAC	CILITY?	Yes		Gol Facility na	ame	SMK Negeri 1 Sigi	.i	.i
HEALTH FAC	CILITY			Gol Facility na	ame			
Street Addr	ess	Jl. Ray	a Palu -	– Palolo KM. 14	Sidera	<u>i</u>	Postco	de 94364

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ⁶	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment		•	
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMK Negeri 1 SIGI
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	1° 0′ 5.731″ S 1	1° 0′ 5.731″ S 119° 55′ 33.377″ E						
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT						
BUDGET NEEDED IN RENAKSI (IDR)	24,048,180,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMK Negeri 1 Sigi should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE Centr	al Sulawesi	KABUPATEN Sigi		KECAMATAN	Sigi Biromaru	
SCHOOL FACILITY?	Yes	Gol Facility name	Gol Facility name SD Negeri Bulupountu Jaya			
HEALTH FACILITY		Gol Facility name				
Street Address	Jl. Kebun S	Sari, Desa Sidera	.i.	Postco	de 94364	

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ⁷	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri BULUPOUNTU JAYA
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	1° 0′ 10.649″ S	1° 0′ 10.649″ S 119° 56′ 31.844″ E						
Damage Severity	HEAVY X MODERATE LIGHT							
BUDGET NEEDED IN RENAKSI (IDR)	568,472,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri Bulupountu Jaya should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Sigi			KECAMATAN	Sig	i Biromaru
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me	SD Negeri Lompio	<u>i</u>	<u>i</u>	
HEALTH FAC	CILITY			Gol Facility na	me				
Street Addre	ess	Jl. Tan	iggul Gu	ımbasa, Lompic)		Post	code	94364

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ⁸	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?	•	No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 5. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 6. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 7. All site plans shall be presented in the same format as SD Negeri LOMPIO
- 8. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	1° 4′ 13.310″ S	1° 4′ 13.310″ S 119° 56′ 9.823″ E						
Damage Severity	HEAVY X MODERATE LIGHT							
BUDGET NEEDED IN RENAKSI (IDR)	967,902,400							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri Lompio should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Sigi			KECAMATAN	Kul	lawi	
SCHOOL FAC	ILITY?	Yes		Gol Facility na	ame	SD Negeri No.1 Boladangko				
HEALTH FAC	HEALTH FACILITY Gol Facility name									
Street Addre	ess Ds. Boladangko			.i.	Posto	ode	94363			

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ⁹	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri No.1 Boladangko
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	1° 26′ 57.966″ S	1° 26′ 57.966″ S 119° 58′ 54.473″ E						
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT						
BUDGET NEEDED IN RENAKSI (IDR)	739,830,400							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri No.1 Boladangko should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN – Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Sigi			KECAMATAN	Kulawi
SCHOOL FAC	CILITY?	Yes		Gol Facility name		SD Negeri 2 Gimpu	i	.i
HEALTH FAC	HEALTH FACILITY Gol Facility name							
Street Addr	ess	Ds. Gi	mpu			.i	Postco	de 94363

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹⁰	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment		•	
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri 2 Gimpu
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	1° 41′ 38.958″ S	1° 41′ 38.958″ S 120° 5′ 56.962″ E							
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT							
BUDGET NEEDED IN RENAKSI (IDR)	967,902,400								

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri 2 Gimpu should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Sigi			KECAMATAN	Kulawi
SCHOOL FAC	CILITY?	Yes		Gol Facility name		SMP Negeri 3 Sigi	<u>i</u>	.i
HEALTH FACILITY Gol Facility name		ame						
Street Addr	ess	Ds. Bolapapu			.i	Postco	de 94363	

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹¹	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			-
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	-
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMP Negeri 3 SIGI
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	1° 26′ 38.324″ S	1° 26′ 38.324″ S 119° 59′ 4.628″ E							
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT							
BUDGET NEEDED IN RENAKSI (IDR)	N/A								

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMP Negeri 3 Sigi should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawesi	i	KABUPATEN Dong g		gala	KECAMAT	AN Si r	enja
SCHOOL FACILITY? Yes G		Gol Facility name SD Negeri 21 Sirenja		·····					
HEALTH FACILITY Gol Facility name									
Street Addr	ess	Dusun	III Labı	uana, Desa Lenc	le Tove	a	I	Postcode	94354

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹²	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri 21 SIRENJA
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 8′ 58.873″ S	0° 8′ 58.873″ S 119° 48′ 22.997″ E							
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT							
BUDGET NEEDED IN RENAKSI (IDR)	2,340,000,000								

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri 21 Sirenja should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Dong g		gala	KECAMATAN	Labuan		
SCHOOL FA	CILITY?	Yes		Gol Facility na	me	SMP Negeri 1 Labuan				
HEALTH FAC	CILITY	•		Gol Facility name						
Street Address Labuan				Postco	de 94352					

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹³	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment		•	
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMP Negeri 1 LABUAN
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 40′ 28.510″ S	0° 40′ 28.510″ S 119° 49′ 57.572″ E					
Damage Severity	HEAVY X MODERATE LIGHT						
BUDGET NEEDED IN RENAKSI (IDR)	2,730,000,000						

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMP Negeri 1 Labuan should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Dong		gala	KECAMATAN	Sin	due Tobata	
SCHOOL FAC	ILITY?	Yes		Gol Facility na	me	ne SMP Negeri Satap 3 Sindue Tobata				
HEALTH FAC	HEALTH FACILITY GoI Facility name									
Street Address Jl. Jumadi no.			41, Tamarenja		Posto	ode	94353			

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹⁴	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMP Negeri SATAP 3 SINDUE TOBATA
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 24′ 48.1″ S 1	0° 24′ 48.1″ S 119° 48′ 22.7″ E					
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT					
BUDGET NEEDED IN RENAKSI (IDR)	1,008,000,000						

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMP Negeri Satap 3 Sindue Tobata should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Parigi Moutong			KECAMA	ATAN K	(asimbar
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me SD Negeri 3 Kasimbar				
HEALTH FAC	ILITY	•		Gol Facility name					
Street Addre	ess	Dusun Lemo				i		Postcode	94462

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹⁵	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri 3 KASIMBAR
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 7′ 8.400″ S 1	0° 7′ 8.400″ S 119° 58′ 41.160″ E						
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT						
BUDGET NEEDED IN RENAKSI (IDR)	908,160,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri 3 Kasimbar should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN – Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Parigi		i Moutong	KEC	AMATAN	Sini	iu
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me	SD Inpres Marantale				
HEALTH FAC	CILITY	•		Gol Facility na	ty name					
Street Addr	ess	Jl. Trans Sulawesi, Kel. Uevolo			.i		Postco	de	94474	

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates	Yes	
		Cadastral Map ¹⁶	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey	•	
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			-
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	-
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?	•	No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Inpres MARANTALE
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 8′ 35.020″ S	0° 8′ 35.020″ S 120° 0′ 0.220″ E					
Damage Severity	HEAVY	HEAVY X MODERATE LIGHT					
BUDGET NEEDED IN RENAKSI (IDR)	825,600,000						

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Inpres Marantale should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Parigi N		i Moutong	KECAMATAI	N Par	rigi Utara
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me	SD Negeri Toboli	i	<u>i</u>	
HEALTH FAC	CILITY	•		Gol Facility na	me				
Street Addr	ess	Jl. Tra	ns Sula	wesi, Desa Tobo	oli	.i	Po	stcode	94471

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning Ownership Agency Commitment Site Assessment DPU Assets Inspection Geophysical Assessment Site/ structures plans Electrical Mains Potable water	GPS Coordinates	Yes	
		Cadastral Map ¹⁷	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri TOBOLI
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 42′ 35.924″ S	0° 42′ 35.924″ S 120° 5′ 33.137″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT			
BUDGET NEEDED IN RENAKSI (IDR)	1,348,480,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri Toboli should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawes	si	KABUPATEN Parigi Mo		i Moutong	KECAM	ATAN	Parigi Barat	
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me	SD Negeri Parigimpuu				
HEALTH FAC	CILITY			Gol Facility name						
Street Addr	ess	Jl. Ma	gau Jan	ggo, Ds. Parigin	go, Ds. Parigimpuu Postcode 9447					

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	# ATTRIBUTE Geographical positioning Ownership Agency Commitment Site Assessment DPU Assets Inspection Geophysical Assessment Site/ structures plans	GPS Coordinates	Yes	
		Cadastral Map ¹⁸	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri PARIGIMPUU
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 48′ 50.677″ S	0° 48′ 50.677″ S 120° 8′ 22.790″ E						
Damage Severity	HEAVY X MODERATE LIGHT							
BUDGET NEEDED IN RENAKSI (IDR)	825,600,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri Parigimpuu should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Parigi I		i Moutong	KECAMATA	N Tor	ue	
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me	SD Negeri Purwosari				
HEALTH FAC	ILITY	•		Gol Facility na	cility name					
Street Addre	ess	Jl. Tra	ns Sula	wesi, Desa Purw	osari	i	Po	ostcode	94372	

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	# ATTRIBUTE Geographical positioning Ownership Agency Commitment Site Assessment DPU Assets Inspection Geophysical Assessment Site/ structures plans	GPS Coordinates	Yes	
		Cadastral Map ¹⁹	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and
 diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial
 consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c)
 consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SD Negeri PURWOSARI
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 58′ 36.981″ S	0° 58′ 36.981″ S 120° 19′ 8.269″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT			
BUDGET NEEDED IN RENAKSI (IDR)	2,421,760,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SD Negeri Purwosari should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN	Parig	i Moutong	KECAM	ATAN T	orue	
SCHOOL FAC	CILITY?	Yes		Gol Facility na	me	SMP Negeri 2 Satap Parigi Selatan				
HEALTH FAC	CILITY	•		Gol Facility na	me	ne				
Street Addr	ess	JL Bo	nebula	Gunung Mulya	Desa S	umbersari		Postcode	94471	

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	# ATTRIBUTE Geographical positioning Ownership Agency Commitment Site Assessment DPU Assets Inspection Geophysical Assessment Site/ structures plans	GPS Coordinates	Yes	
		Cadastral Map ²⁰	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- 1. The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and diligent in producing a "3600" assessment of each site (a) National, Provincial and community stakeholders have provided initial consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c) consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMP Negeri 2 Satap Parigi Selatan
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 56′ 18.352″ S	0° 56′ 18.352″ S 120° 16′ 46.960″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT			
BUDGET NEEDED IN RENAKSI (IDR)	970,080,000							

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMP Negeri 2 Satap Parigi Selatan should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4



(for inclusion in RFP Scope of Services for each site)

Prepared by: PMU Palu Date: 26-July 2019.

PROVINCE	Central	Sulawe	si	KABUPATEN Pari g		Moutong	KECAMATAN	Par	igi Utara
SCHOOL FACILITY? Yes		Yes		Gol Facility na	me	SMP Negeri 1 Parigi	P Negeri 1 Parigi Utara		
HEALTH FACILITY			Gol Facility name						
Street Address Jl. Trans Su			ıns Sula	awesi no. 266, Desa Toboli		ooli	Postco	ode	94471

SITE DATA ASSESSMENT

ITEM#	ATTRIBUTE	VERIFIABLE EVIDENCE	YES	NO
1	Geographical positioning	GPS Coordinates		
		Cadastral Map ²¹	Yes	
		Technical description: boundary alignments; adjoining lots.	Yes	
		Survey boundary monuments located & clear of debris/	Yes	
		vegetation.		
2	Ownership	Certificate of Title copy attached		No
		Clear and Clean title guaranteed by Provincial Government (#5)	Yes	
		Acquisition of new site if high risk is apparent on existing site?		No
		Enlargement or realignment of site boundaries required?		No
3	Agency Commitment	Proposed works are Included in RENAKSI? (#1)	Yes	
		Buildings certified as government owned with major damage (#2)	Yes	
		Funds are not duplicating other budget sources (#3)	Yes	
		There is a safe & secure location (#4) Subject to Geological Survey		
		Willingness for removal of asset to be reconstructed (#6)	Yes	
		Local authority willing to receive & maintain rebuilt buildings (#7)	Yes	
		Development approval and permit costs by local authority (#8)	Yes	
4	Site Assessment			
	DPU Assets Inspection	Serviceability & forensic assessment certification?	Yes	
	Geophysical Assessment	Report on fissures, faults/ fault lines, landslip, liquefaction risks?		
5	Site/ structures plans	Original as built site layout plan available in digital form?		No
		Current as built site layout plan available in digital form?		No
		Original as built structures plans available in digital form?		No
		Updated as built structures plans available in digital form?		No
		Each structure has digital general arrangement & detail drawings?		No
		Each structure type can be identified by drawing no. and/ or code?		No
6	Electrical Mains	Inspected and rendered functional & safe by power authority?	Yes	
7	Potable water	Reticulated water with ample flow & operational service points?		No
		Rainwater storage collection and storage?		No
8	Sewerage & Septic Tanks	Adequately functional with no health hazard?		No
	Telephone land lines	Connections are in working order and cables well secured?	Yes	
9	Road access	External access road is trafficable and in fair to good condition?	Yes	
10	Demolition & Clean up	Most site areas have not been cleaned up/ are not trafficable		No
11	ESM Framework	Draft document circulated to Pemda /local agencies for comment?		No
12	Disabled Users	Building users have cited special needs for handicapped persons?		No
13	Cultural Identifiers	Stakeholders request cultural character in building design?		No
14	Site Greening	Stakeholders request guidance on shade trees &food gardens?		No
15	Alternative Energy	Stakeholders OK with solar panels & battery storage?	Yes	

- The above checklist and the attached graphics has the purpose of ensuring that (a) we in PETRA have been thorough and
 diligent in producing a "360" assessment of each site (a) National, Provincial and community stakeholders have provided initial
 consensus input to the design process, which will be augmented by the DCS consultants' working engagement, and (c)
 consultant responses to the RFP shall be well informed
- 2. We need to have site plans in a common format, with a common numbering convention and reference to parent agency drawing numbers or type designation. Numbering shall go anticlockwise from the bottom LH corner

- 3. All site plans shall be presented in the same format as SMP Negeri 1 Parigi Utara
- 4. Please delete this "GUIDANCE" to add brief clarifying remarks on the above responses, particularly any "NO" responses which are not self-evident. Please also where appropriate state what further actions will be taken by you.

GPS COORDINATE	0° 42′ 31.576″ S 120° 5′ 42.792″ E						
Damage Severity	HEAVY	Х	MODERATE		LIGHT		
BUDGET NEEDED IN RENAKSI (IDR)	1,444,800,000						

Summarized description – main tasks: MUST ACCURATELY REFLECT TASK BREAKDOWN IN BILL OF QUANTITIES

Design of the buildings at SMP Negeri 1 Parigi Utara should be in accordance with regulations and standards from Ministry of Public Works and Ministry of Education.

SITE PLAN - Please make sure every site for both Education, Health & Environment contexts are uniformly presented

Please see Annex 4.4

