## Lot 9 - Refurbishment and relocation of furniture requirements

Note All rates is to be rounded one decimal place. The contractor will collect all existing furniture (lot 9) from different UN offices in Ha Noi to contractor's storage and return the refurbished items to UN House after completion of refurbishment. Payment for refurbishment works are based on actual quantities agreed by the

Fabric type 1: Woven image Metropolis 579 Gold; 100% Pure New Wool

Fabric type 2: Woven image Metropolis 390 Green; 100% Pure New Wool

Fabric type 3:Woven image Metropolis 193 Rouge; 100% Pure New Wool

Fabric type 4: Woven image Metropolis 542 Black; 100% Pure New Wool

Unit Rate for refurbishment is inclusive of material and accessory

No.	Item	Image	Q'ty	Unit	Refurbishment Description
1	UNFPA				
1.1	UNFPA TC1		1	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one  Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Arm height adjustment: replace broken arm so that arm can adjust height independently; no scratch on arm finishes  Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Replace broken caster with new one  Five Star Base: Replace broken base with new one. Colour to Headrest: Replace broken headrest with new one. Joint between back and headrest must work well  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment
1.2	UNFPA TC2		24	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one  Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Arm height adjustment: replace broken arm so that arm can adjust height independently; no scratch on arm finishes  Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Replace broken caster with new one

Div 5 Page 1 of 9

No.	Item	lmago	Q'ty	Unit	Polyrhighment Description
INO.	пеш	Image	Q ty	Offic	Refurbishment Description  Five Star Base: Replace broken base with new one. Colour to
					<u> </u>
					Headrest: Replace broken headrest with new one. Joint between back and headrest must work well
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
					refurbishment
					Replace broken mechanisms swivel-tilt with new one so that
					swivel joint work lightly
					Seat height adjustment with a pneumatic height mechanism:
					Replace broken cylinder with new one so that new cylinder can
					work smoothly and lightly
					Replace broken passive seat edge angle with new one
		-			Back adjustment: replace broken part with new one so that the
		202			backrest can inclinate backward. Joint between backrest and seat
					work smoothly.
1.3		- 1000			Upper back tension: replace broken upper back tension with new
	UNFPA TC3		4		one so that it can allow user to slightly inclinate backward; protect
		all years			user from suddenly falling backward
					Arm height adjustment: replace broken arm so that arm can adjust
					height independently; no scratch on arm finishes
					Replace the existing upholstery with new one; colour(black)/type
					to match the original. No scratch on seat and lower foam.
					Replace broken caster with new one
					Five Star Base: Replace broken base with new one. Colour to
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
					refurbishment
					Replace broken mechanisms swivel-tilt with new one so that
					swivel joint work lightly
					Seat height adjustment with a pneumatic height mechanism:
					Replace broken cylinder with new one so that new cylinder can
					work smoothly and lightly
					Replace broken passive seat edge angle with new one
					Back adjustment: replace broken part with new one so that the
					backrest can inclinate backward. Joint between backrest and seat
					work smoothly.
١	LINIEDA TOA		_		Upper back tension: replace broken upper back tension with new
1.4	UNFPA TC4		5	Set	one so that it can allow user to slightly inclinate backward; protect
					user from suddenly falling backward
					Arm height adjustment: replace broken arm so that arm can adjust
					height independently; no scratch on arm finishes
					Replace the existing upholstery with new one; colour(black)/type
					to match the original. No scratch on seat and lower foam.
					Replace broken caster with new one
					Five Star Base: Replace broken base with new one. Colour to
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
					refurbishment

Div 5 Page 2 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
1.5	UNFPA Type1 and type 2		27	Set	Seat and back upholstery:  - Replace the existing seat and back upholstery with fabric type 1 or equivalent  - No scratch on seat and lower foam  Powder Coated of Sled base: Replace broken one with new one. Colour to match  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment
1.6	UNFPA Type3		10	Set	Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Chrome of Sled base: Replace broken one with new one. Colour to match  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
2	UNIDO				
2.1	UNIDO Type1		8	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one  Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Replace broken arm; no scratch on arm finishes  Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Replace broken caster with new one  Five Star Base: Replace broken base with new one. Colour to  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
2.2	UNIDO Type2		8	Set	Seat and back upholstery: - replace the existing seat and back upholstery with fabric type 1 or equivalent - No scratch on seat and lower foam  Powder Coat of 4 legs: Replace broken leg with new one. Colour to match  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.

Div 5 Page 3 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
					Replace broken mechanisms swivel-tilt with new one so that
					swivel joint work lightly
					Seat height adjustment with a pneumatic height mechanism:
					Replace broken cylinder with new one so that new cylinder can
					work smoothly and lightly
					Replace broken passive seat edge angle with new one
		The State of the S			Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat
					work smoothly.
					Upper back tension: replace broken upper back tension with new
2.3	UNIDO		4	Set	one so that it can allow user to slightly inclinate backward; protect
	Type3				user from suddenly falling backward
					Replace broken arm; no scratch on arm finishes
					Seat and back upholstery:
					Replace the existing upholstery with new one; colour(black)/type
					to match the original. No scratch on seat and lower foam.
					Replace broken caster with new one
					Five Star Base: Replace broken base with new one. Colour to
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
					refurbishment.
3	WHO				
					Seat Upholstery:
	WHO Type1		18		- replace the existing seat and back upholstery with fabric type 1
					or equivalent
					- No scratch on seat and lower foam
3.1				Set	Power Coated of Sled based: Replace broken one with new one.
					Colour to match
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
					refurbishment.
					Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly
					Seat height adjustment with a pneumatic height mechanism:
					Replace broken cylinder with new one so that new cylinder can
					work smoothly and lightly
					Replace broken passive seat edge angle with new one
					Back adjustment: replace broken part with new one so that the
					backrest can inclinate backward. Joint between backrest and seat
					work smoothly.
					Upper back tension: replace broken upper back tension with new
3.2	WHO Type2		60	Set	one so that it can allow user to slightly inclinate backward; protect
					user from suddenly falling backward Replace broken arm; no scratch on arm finishes
					Seat Upholstery:
					- replace the existing seat and back upholstery with fabric type 4
					or equivalent
					- No scratch on seat and lower foam
					Replace broken caster with new one
					Five Star Base: Replace broken base with new one. Colour to
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
					refurbishment.

Div 5 Page 4 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
4	IOM				
4.1	IOM 6458, type 1 and type 2	3	17	Set	Seat Upholstery: - replace the existing seat and back upholstery with fabric type 1 or equivalent - No scratch on seat and lower foam  Powder Coat of Sled base: Replace broken one with new one. Colour to match  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
4.2	6499		1	Set	Cleaning and repaint; no scratch on new paint  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
5	UNDP				
5.1	5255		6	Set	Cleaning and repaint for wood so that no scratch on repaired structure  Seat Upholstery: - replace the existing seat upholstery with fabric type 2 or equivalent  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
5.2	5411		1	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly Replace broken passive seat edge angle with new one Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Arm height adjustment: replace broken arm so that arm can adjust height independently; no scratch on arm finishes  Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Replace broken caster with new one  Five Star Base: Replace broken base with new one. Colour to Headrest: Replace broken headrest with new one. Joint between back and headrest must work well  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.

Div 5 Page 5 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
		Name of Street			Cleaning and repaint for wood so chat no scratch on repaired structure
5.3	5430		8	Set	Seat Upholstery: - replace the existing seat and back upholstery with fabric type 2 or equivalent - No scratch on seat and lower foam
					Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
					Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism:
					Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one
5.4	5444				Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new
			89		one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Replace broken arm; no scratch on arm finishes
					Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type
					to match the original. No scratch on seat and lower foam.  Replace broken caster with new one
					Five Star Base: Replace broken base with new one. Colour to
					Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
					Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly
					Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly
					Replace broken passive seat edge angle with new one
					Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.
5.5	5596		4		Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward
		-			Replace broken arm; no scratch on arm finishes
					Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type
					to match the original. No scratch on seat and lower foam.
					Replace broken caster with new one Five Star Base: Replace broken base with new one. Colour to
					Transportation of furniture from UN Agencies to the Contractor's
					location for refurbishment and to UN House after completion of
	<u> </u>		ļ		refurbishment.

Div 5 Page 6 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
		0			Cleaning and repaint for wood so chat no scratch on repaired structure
5.6	5634		2	Set	Seat Upholstery: - replace the existing seat and back upholstery with fabric type 1 or equivalent - No scratch on seat and lower foam
					Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
					Cleaning and repaint for wood so chat no scratch on repaired structure
5.7	5637		1	Set	Seat Upholstery: - replace the existing seat and back upholstery with fabric type 1 or equivalent - No scratch on seat and lower foam
					Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
6	UNICEF				
	5703		10	10 Set	Cleaning and repaint for wood so chat no scratch on repaired structure
6.1					Seat Upholstery: - replace the existing seat and back upholstery with fabric type 3 or equivalent - No scratch on seat and lower foam
		(picture of 4sets, bid/work excludes table)			Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
				Sea - rep or e - No Trar loca	Cleaning and repaint for wood; No scratch on repaired structure
6.2a	5778a		22		Seat Upholstery: - replace the existing seat and back upholstery with fabric type 1 or equivalent - No scratch on seat and lower foam
					Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
	5778b		22	Set	Cleaning and repaint for wood; No scratch on repaired structure
6.2b					Seat Upholstery: - replace the existing seat and back upholstery with fabric type 2 or equivalent
					Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.

Div 5 Page 7 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
6.3	5788, 5821		80	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one  Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Replace broken arm; no scratch on arm finishes  Seat Upholstery: - replace the existing seat and back upholstery with fabric type 2 or equivalent - No scratch on seat and lower foam  Replace broken caster with new one  Five Star Base: Replace broken base with new one. Colour to  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
6.4	5877		8	Set	Cleaning and repaint for frame; No scratch on repaired structure  Seat Upholstery: - replace the existing seat and back upholstery with fabric type 1 or equivalent - No scratch on seat and lower foam  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
6.5	5991		8	Set	Cleaning and repaint for wood; No scratch on repaired structure  Seat Upholstery: - replace the existing seat upholstery with fabric type 2 or equivalent - No scratch on seat and lower foam  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
6.6	6002		8	Set	Cleaning and repaint for wood; No scratch on repaired structure  Seat Upholstery: - replace the existing seat and back upholstery with fabric type 2 or equivalent - No scratch on seat and lower foam  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment (lump sum).

Div 5 Page 8 of 9

No.	Item	Image	Q'ty	Unit	Refurbishment Description
7	FAO				
7.1	6842, 7159		28	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Arm height adjustment: replace broken arm so that arm can adjust height independently; no scratch on arm finishes  Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Replace broken caster with new one  Five Star Base: Replace broken base with new one. Colour to  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of refurbishment.
8	UNWOMEN				returbishment.
8.1	5444		14	Set	Replace broken mechanisms swivel-tilt with new one so that swivel joint work lightly  Seat height adjustment with a pneumatic height mechanism: Replace broken cylinder with new one so that new cylinder can work smoothly and lightly  Replace broken passive seat edge angle with new one  Back adjustment: replace broken part with new one so that the backrest can inclinate backward. Joint between backrest and seat work smoothly.  Upper back tension: replace broken upper back tension with new one so that it can allow user to slightly inclinate backward; protect user from suddenly falling backward  Replace broken arm; no scratch on arm finishes  Seat and back upholstery: Replace the existing upholstery with new one; colour(black)/type to match the original. No scratch on seat and lower foam.  Replace broken caster with new one  Five Star Base: Replace broken base with new one. Colour to  Transportation of furniture from UN Agencies to the Contractor's location for refurbishment and to UN House after completion of

Div 5 Page 9 of 9