



Empowered lives.
Resilient nations.

Date: 20th August 2019

ADDENDUM 01 - RESPONSE TO REQUEST FOR CLARIFICATIONS:
ITB-200-19 PHASE-II-REHABILITATION OF 361 HOUSING UNITS IN AL KHAZRAG
NEIGHBORHOOD-OLD CITY-WEST MOSUL, NINEWA GOVERNORATE


All potential bidders interested are hereby informed to take note of the response to the request for clarifications during the site visit as summarized below;

No.	BIDDER QUESTIONS ASKED	UNDP response to request for clarification
1	What does the windows repairing items include?	The scope for the window repairs will include; a) Repair damaged steel windows including welding all parts of the window and frame. b) Replace all anti-insect wire mesh for openable parts of the window c) Replacement Change all handles d) Replacement of crystal-clear glass 4mm including glass fix paste e) Repair/replacement of all window frames with glass. f) Repair/replacement of all window frames with paint.
2	How will you deal with houses containing items rehabilitated by owner or other NGO?	Please see ITB Section 3: Bid Data Sheet item # 25-page 21 clarifying that; prior to implementation the BoQ will be re- assessed for items already rehabilitated. No additional works will be substituted for the items which have been undertaken by the home owner/other NGO.
3	How can the mortar holes in the roofs be repaired in our work?	The mortar holes in the roofs will be repaired by removal and recast of the damaged parts using new cast with "waterproof cement ". Please see BoQ item # 10 including for the holes information on the slab.
4	Are there some houses containing EH Cases not removed yet?	The scope of works includes some houses containing explosive hazards (EH). Such houses, repair cannot start until the EH is removed by the special removal teams.
5	How many houses are heavily damaged in the total houses of the project?	The total number of heavily damaged houses is estimated to range (10-15) %.

No.	BIDDER QUESTIONS ASKED	UNDP response to request for clarification
6	What are the items for repairing sun sheds?	There are two (2) types of repairs: a) Supply new corrugate sheet with new frame. b) Replace the corrugated sheet only.
7	Where can the contractor dump the rubbles of the works?	During implementation, the Municipality Directorate will confirm the authorized locations to dump the rubbles.

This Addendum - OI forms an integral part of the **ITB 200/19**.

All other Terms and Conditions in this ITB will remain unchanged.

Yours sincerely,

Piero Emanuele Franceschetti
Head of Service Center, Iraq