

Dated: 29 April, 2018

Addendum-02

IRQ10-ITB-229-18 Rehabilitation of General Authority of Underground Water-Ninawa Branch, East Mosul

Clarification of Line Item of BOQ

Please be advised of the following questions asked by the bidder and UNDP clarifications:

Item No.	Bidders Question	UNDP Response
Item No. 5 of Civil Works	Referring to item 5 from civil work there is no drawing for Reinforced Concrete kindly send the drawing to us to know the requirements of steel reinforcement.	The drawing named " DWG-Detail of Retaining Wall-1 " which was already attached in the e-tendering module includes the item-5 steel reinforcement requirements; however; the foundation size in the B.O.Q civil works for item 5 to be read 0.50m*2.5 m instead of 60*50cm . Please find attached the updated BoQ correcting item 5, foundation size. Please use this updated BoQ in your submission.

This addendum -02 forms an integral part of the ITB 229-18. All other Terms and Conditions in this ITB will remain unchanged.

Yours Sincerely



Piero Emanuele Franceschetti
Head of Service Center