

ITB No. ITB-284/18- Rehabilitation of Sinjar Cement Substation, Ninawa Governorate Time of Site Visit Start End		Date of Site Visit 23 <sup>th</sup> July . 2018	Escorted by Military Forces YES□, NO ⊠	
		Name(s) and job title of Gov. Rep.		
Names of companies attended	Rep. name	Mobile/Email	Signature	
Binas	Aras Ahmad	Bniasco@gmail.com 07504056988		
Kiman Company	Osman Ibrahim	Kimancompany@yahoo.com 07504264183		
Alshamsh co	Ghassan R.R	<u>info@shamsh.net</u> 07508333737		
Rihab ninawe	Omar amjed	Rihabninawa@gmail.com 07706144795		

## **QUESTIONS AND ANSWERS**

No.	BIDDER QUESTIONS ASKED	UNDP RESPONSES GIVEN
1		
#	All cables have to be changing ?	No (Only Low Voltage ) LV Cables according to the Tender
#	Can we repair air condition?	AC (Split Unit ) have to be using
#	Line Traps need to change	Only two set of them according to the Tender
#	No Of Capacitor bank have to be supply	Four cell of capacitor bank have to supply
#	How Many Battery charger need	Two Set of battery charger have to be supply
#		
#		
#		
#		

Attendance sheet for the bidders who visited the sites: Attached

Photos during the site visit for the current situation: Attached

The authorized focal person responsible for preparing attendance sheets before the site visit and photography

Certification of Minutes as a true record of the proceedings of the meeting/site visit:

Prepared by:

Kamaran Ysin

Tolaz Ashty

Signature:Position: Electrical EngineerDate: 23th July , 2018Record of Pre-Bid Meeting/site visit to be posted on the websites.

## Site Visit Report

ITB No.	te of Site Visit 23/7/20 Forces?		Yes No
Time of Site Visit	Name(s) and job title of Gov. Rep.		
10 AM 12 AV	They ser	not there	
Names of companies attended	Rep. name	Mobile/Email	Signature
BNIAS	Aras Ahmad	briasco Qymaid	an g
		07504056988	2
Kiman Co	OS man Ibrahim	Kiman Compango Yahoo, com	Stork
		07504264183	A.
Al Shanshe	Ghasson R.R.	27508333737	KL
Rihab ninawa	OMPAR AMSED	into a shows h.	whet
		Rihab nina wa 2gami.	
		07706144795	

## **QUESTIONS AND ANSWERS**

No.	BIDDER QUESTIONS ASKED	UNDP RESPONSES GIVEN
1		• · · · · · · · · · · · · · · · · · · ·
#	All cooles hore to be	No Conty low volteg. ) LV
1.1	changing	Cobles acording to terde
#	Can we repair oir candition	AC (SPlitunit) hove tobe Using
#	Line Trops need to chang	only Tows set of them according to the tender
#	No of copositor Bank have to be supply	four GN of collactor bank have & be supply
#	How Mony Battery	Two Set of battery
	charger need	chorger have to be SUNP
#		
#		
#		

Attendance sheet for the bidders who visited the sites: Attached

Photos during the site visit for the current situation: Attached

The authorized focal person responsible for preparing attendance sheets before the site visit and photography

Certification of Minutes as a true record of the proceedings of the meeting/site visit:

Prepared by: Kamaran Ysin

**Civil Eng** 

Signature:Position: Electrical EngineerDate: 23th July , 2018Record of Pre-Bid Meeting/site visit to be posted on the websites.











