
UN-HABITAT
FOR A BETTER URBAN FUTURE
Houses assessment in block C&D in znjili neighborhood in mosul city as of january 2019
Znjili blocks
Znjili neighborhood
Neighborhood boundary
Building boundary
Minor damaged in block C&D= 271
Sever damaged
Packages A(18-19-20-21-22-23-24-25)
© UN-Habitat / January 2019
Ibn-Al-Atheer 1
P18
P19
P20
P21
P22
P23
P24
P25
P26