Site Visit Report



Location of Site Visit : Rehabilitation of Electrical Network in Al-Rayhana District – Anah .

ITB No. 18-20 - : Rehabilitation of Electrical Network in Al- Rayhana District - Anah		Date of Site Visit	27\ 1 \2020	Escorted by Military forces?		Yes No _/
Time of Site Visit Start End		Name(s) and job title of G			iov. Rep.	
10:00 AM	12:00 PM	Ghassan Kanoosh Employee DG		at Anah Electri	city	
Names of companies attended		ed	Rep. name		Mobile/Email	Signature
Al-Fityan Co.			Mohammed Khalil		07702883881	
Al-Dhayaghim Co.			Mohammed Ibrahim		07827427145	
Tareek Al-Tebr Co.			Waad Khairi Dawood		07813669902	
Al-Turath Al-Areeq			Abulsattar Taha		07807722589	
Al-Juna Co.			Omer Khudair		07801723946	
Al-Faid Co.			Ammar Nori		07901111139	
Al-Yamam Co.			Khaled Fayadh		07816954768	
Maabr Al-Jood Co.			Bilal Salim		07816332475	
Ewan Co.			Hasan Mamdoh		07817852875	
Al-Barqa'a Co.			Qusai Attallah		07824388834	
Sar Al-Baraa Co.			Ali Emad Abdulwahid		07830555053	
Mishkat Al-Noor Co.			Ahmed Jammal		07827424443	
Ummet Al-Salam Co.			Emad Gharib		07831915231	
Al-AJamm Co.			Ameen Majid		07817715120	
Qalat Najed Co.			Ahmed Mahmood		07719277769	
Abeer Al-Furat Co.			Abdulhameed Ismail Khaleel		07817715120	
Tareq Al-Eid Co.			Mohammed Rajab		07802442777	
Joharat Al-Habbania Co.			Arif Mukhlif		07902307979	
Tareq Zamzam Co.			Mustafa Hameed		07804110522	
Al-Mahara Co.			Safaa Hassan		07811119990	
Al-Handal Co.			Aead Abd Al-Rahman		07705246568	
Miknas Co.			Mustafa Mansi		0781705114	

	QUESTIONS AND ANSWERS						
No.	BIDDER QUESTIONS ASKED	UNDP RESPONSES GIVEN					
1	Whats the damaged parts that must be dismantled and removed in the network ?	- The Bidders reps. Were - informed that the damaged parts are some galvanized poles , conductors , insulators etc . according to BoQ and the directions of the supervision committee .					
2	What's the type of the work in the network ?	- The bidders reps. were informed that the work includes to supply and install poles , AAC , ACSR wires ,250 KVA transformer's etc as detailed in BoQ and according to compliance sheet .					
3	Where is the locations of the damaged network that will be rehabilitated?	-The Bidders reps. were token to the locations of the damaged network and given a brief about that.					

Certification of Minutes as a true record of the proceedings of the meeting/site visit:

Prepared by:

Name: Alaa Naji Abd – Aljaleel

Position: Site Engineer (Anah and Rawah)

Signature: 🧕 A

Date: 27 \1 \ 2020

Record of Pre-Bid Meeting/site visit to be posted on the websites.